

Piezas de aluminio mecanizado CNC



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYA-130820
 Supplier : XY-GLOBAL

Inspection Date:15th Sep-, 2013
 Inspector:LEO

| | |
|---|-----------------------------------|
| Inspection only for: PO . XYA-130820 Item No.130020 | <u>Inspection Result:</u> PASS |
|---|-----------------------------------|

| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| 130020 | 500PCS | 3% inspection | 0pcs | No failure | 500pcs |

| |
|--|
| Appearance Inspection : No failure, |
| Dimension Inspection: No failure , below measurement report for reference. |
| Assembly Test: No failure |
| Inspection Summary The inspection sample plan is 100% inspection. |

| | |
|---|--|
| Digital photo records : | |
|  |  |
| 1. Packing | 2. Product: |
|  |  |
| 3. Product: | 4. Product: |
|  |  |
| 5. Product : | 6. Product: |