

Inspection Report

Report No.: 140507-01  
 Supplier :







Inspection Date: 07<sup>th</sup> May 2014  
 Inspector: Ken Tung

Inspection only for: frame sample Item No. XY-Frame-041	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-Frame-041	10sets	100%	0pcs	1pcs poor finish	10pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure
<b>Leakage Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan are follow AQL . The result of inspection is acceptable.

Digital photo records :

	
1. Product	2. Product
	
3. Product	4. Product
	
5. Product	6. Carton

