

Inspection Report

Report No.: XYBA-141122
 Supplier : XY-GLOBAL

Inspection Date: 19th Dec-, 2014
 Inspector:LEO

Inspection only for: PO . XYBA-141122 Item No. XY21ZC040	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC040	5000Pcs	7% inspection	0pcs	No failure	6000Pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

品名	CNC 部品
品番	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 POM
材質	
仕様	
公差	CNC 標準
表面処理	gague
MOQ	
公差	+/- 0.01
リードタイム	T / T 50
加工方法	CNC
検出	CNC
梱包	20-25
加工機	CNC
1.Name OEM CNC	
2.Process CNC	
3.Material AL6061 AL6065 AL6063 AL7075 POM	
4.Surface nickle	
5.Tolerance +/- 0.01	
6. 100	
7.Specification OEM service	
8. 25 30	
9. CNC accessoried	
10. Austrial EU	
11. ISO 9001	
ISO 1. 10	
2. surface finishment kinds available	
4.	
5.	
6.	
7.	
CNC	
CNC	
CNC ISO9001	
CNC	
CNC OEM	