

Inspection Report




Report No.: XYN-140510
Supplier : XY-GLOBAL

Inspection Date: 7th Jun, 2014
Inspector: Ken

Inspection only for: PO . XYN-140510 Item No.XY-140320	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-140320	40000PCS	1% inspection	0pcs	No failure	40000pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

