

Inspection Report







Report No.: XYS-130519
Supplier : XY-GLOBAL

Inspection Date: 09th Jun, 2013
Inspector: Leo

Inspection only for: PO . XYS-130519 Item No.XY-1303580	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-1303580	800PCS	5% inspection	0pcs	No failure	800pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

ชื่อ	บริษัท ออโตเมติก เทคโนโลยี จำกัด OEM
ประเภท	ADC12 A380
วัสดุ	ADC12
ขนาด	ตามแบบ
สี	ตามแบบ
กระบวนการ	CNC
MOQ	1000
ความแม่นยำ	+/- 0.01
ระยะเวลา	T / T 50% T / T 50%
สถานที่	CNC
การรับประกัน	ตามมาตรฐาน
ราคา	ตามแบบ
น้ำหนัก	20-25g T / T 50g
การบรรจุ	ตามแบบ
1.Name บริษัท ออโตเมติก เทคโนโลยี จำกัด OEM	
2.Process CNC	
3.วัสดุ ADC12 A380	
4.Surface นิกเกิล	
5.Tolerance +/- 0.01	
6.ขนาด 100	
7.Specification OEM	
8.ระยะเวลา 25-30 วัน	
9.การรับประกัน ตามแบบ	
10.มาตรฐาน Austrial EU	
11.&NBSP ISO 9001	
ISO 10	
2	
3 surface finishment kinds available	
4	
5	
6	
7	
ISO 9001	
OEM	