

**Inspection Report**

Report No.: XYD-140523  
 Supplier : XY-GLOBAL

Inspection Date: 15<sup>th</sup> Jun, 2014  
 Inspector: Leo

Inspection only for: PO . XYD-140523 Item No.5214001	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
5214001	6000PCS	1% inspection	0pcs	No failure	6000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	ADC12 A380 CNC加工品
仕様	ADC12 A380
数量	1000個
納期	約 20-25日
加工方法	CNC加工
公差	+/- 0.01mm
表面処理	ニッケルメッキ
検出率	100%
仕様書	OEM仕様書
梱包	25個/箱
付属品	accessories
認証	Austrial EU
規格	ISO 9001
ISO	1. 10
2.	
3. surface finishment	kindls available
4.	
5.	
6.	
7.	
品名	
仕様	
数量	
納期	
加工方法	ISO9001
公差	
OEM	