

Inspection Report

Report No.: XYSJ-140715
Supplier : XY-GLOBAL

Inspection Date: 25th Aug, 2014
Inspector: Leo

Inspection only for: PO . XYSJ-140715 Item No. XY11KA011	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11KA011	33000PCS	5% inspection	0pcs	No failure	33000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. The test report

品名	各種規格の部品を製造するOEM工場
品名	各種規格のADC12/A380
品名	各種規格の部品
品名	各種規格の部品を製造する工場
品名	各種規格の部品を製造する工場
品名	CNC加工の部品を製造する工場
品名	各種規格の部品を製造する工場
品名	各種規格の部品を製造する工場
MOQ	100
公差	+/- 0.01
公差	T / T 50 / T / T 50
品名	CNC加工の部品を製造する工場
品名	各種規格の部品を製造する工場
品名	各種規格の部品
品名	20 / 25 T / T 50
品名	各種規格の部品
1. Name: 各種規格のOEM工場	
2. Process: CNC加工	
3. Material: ADC12/A380	
4. Surface: 各種規格の部品を製造する工場	
5. Tolerance: +/- 0.01	
6. 各種規格の部品	
7. Specification: OEMサービス	
8. 各種規格の部品	
9. 各種規格の部品	
10. 各種規格の部品	
11. ISO 9001	
ISO 1. 10	
2. 各種規格の部品	
3. surface finishment: kinds available	
4. 各種規格の部品	
5. 各種規格の部品	
6. 各種規格の部品	
7. 各種規格の部品	
8. 各種規格の部品	
9. 各種規格の部品	
10. ISO 9001	
11. 各種規格の部品	
OEM工場	

Safety is our serious job for our worker and engineer team

