

Inspection Report

Report No.: XYZI-140328
 Supplier : XY-GLOBAL

Inspection Date: 24th Apr, 2014
 Inspector: Leo

Inspection only for: PO . XYZI-140328 Item No.1400351	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1400351	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	OEM
品番	ADC12 A380
材質	
表面処理	
加工方法	CNC
公差	gague
MOQ	
寸法	+/- 0.01
リードタイム	T / T 50
加工機	CNC
加工条件	
寸法	
寸法	20 25 T / T 50
寸法	
1.Name OEM	
2.Process CNC	
3.Material ADC12 A380	
4.Surface nicle	
5.Tolerance +/- 0.01	
6. 100	
7.Specification OEM serice	
8. 25 30	
9. accessoried	
10. Austrial EU	
11. ISO 9001	
ISO 1. 10	
2.	
3. sureface finishment kinds available	
4.	
5.	
6.	
7.	
8.	
9. ISO9001	
10.	
OEM	