

Inspection Report

Report No.: XYI-140318
 Supplier : XY-GLOBAL




Inspection Date: 15th Apr, 2014
 Inspector: Leo

Inspection only for: PO . XYI-140318 Item No.142160	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
142160	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

Part Name	ADC12 A380 OEM
Material	ADC12 A380
Quantity	
Surface	nickle
Tolerance	+/- 0.01
MOQ	
Lead Time	T / T 50
Process	CNC
Specification	OEM
Accessories	
Material	ADC12 A380
Surface	nickle
Tolerance	+/- 0.01
MOQ	
Lead Time	T / T 50
Process	CNC
Specification	OEM
Accessories	
Material	ADC12 A380
Surface	nickle
Tolerance	+/- 0.01
MOQ	
Lead Time	T / T 50
Process	CNC
Specification	OEM
Accessories	
Material	ADC12 A380
Surface	nickle
Tolerance	+/- 0.01
MOQ	
Lead Time	T / T 50
Process	CNC
Specification	OEM
Accessories	