

Inspection Report

Report No.: XYL-150718
 Supplier : XY-GLOBAL



Inspection Date: 3th Sep, 2015
 Inspector: Leo

Inspection only for: PO . XYL-150718 Item No. XY11LM018	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM018	11000PCS	1% inspection	Opcs	No failure	11000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :



检查报告

NO.	规格	数量	合格	不合格	不良率	备注
1	XY11LM018	11000	11000	0	0.00%	
2	XY11LM018	11000	11000	0	0.00%	
3	XY11LM018	11000	11000	0	0.00%	
4	XY11LM018	11000	11000	0	0.00%	
5	XY11LM018	11000	11000	0	0.00%	
6	XY11LM018	11000	11000	0	0.00%	
7	XY11LM018	11000	11000	0	0.00%	
8	XY11LM018	11000	11000	0	0.00%	
9	XY11LM018	11000	11000	0	0.00%	
10	XY11LM018	11000	11000	0	0.00%	
11	XY11LM018	11000	11000	0	0.00%	
12	XY11LM018	11000	11000	0	0.00%	
13	XY11LM018	11000	11000	0	0.00%	
14	XY11LM018	11000	11000	0	0.00%	
15	XY11LM018	11000	11000	0	0.00%	
16	XY11LM018	11000	11000	0	0.00%	
17	XY11LM018	11000	11000	0	0.00%	
18	XY11LM018	11000	11000	0	0.00%	
19	XY11LM018	11000	11000	0	0.00%	
20	XY11LM018	11000	11000	0	0.00%	
21	XY11LM018	11000	11000	0	0.00%	
22	XY11LM018	11000	11000	0	0.00%	
23	XY11LM018	11000	11000	0	0.00%	
24	XY11LM018	11000	11000	0	0.00%	
25	XY11LM018	11000	11000	0	0.00%	
26	XY11LM018	11000	11000	0	0.00%	
27	XY11LM018	11000	11000	0	0.00%	
28	XY11LM018	11000	11000	0	0.00%	
29	XY11LM018	11000	11000	0	0.00%	
30	XY11LM018	11000	11000	0	0.00%	
31	XY11LM018	11000	11000	0	0.00%	
32	XY11LM018	11000	11000	0	0.00%	
33	XY11LM018	11000	11000	0	0.00%	
34	XY11LM018	11000	11000	0	0.00%	
35	XY11LM018	11000	11000	0	0.00%	
36	XY11LM018	11000	11000	0	0.00%	
37	XY11LM018	11000	11000	0	0.00%	
38	XY11LM018	11000	11000	0	0.00%	
39	XY11LM018	11000	11000	0	0.00%	
40	XY11LM018	11000	11000	0	0.00%	
41	XY11LM018	11000	11000	0	0.00%	
42	XY11LM018	11000	11000	0	0.00%	
43	XY11LM018	11000	11000	0	0.00%	
44	XY11LM018	11000	11000	0	0.00%	
45	XY11LM018	11000	11000	0	0.00%	
46	XY11LM018	11000	11000	0	0.00%	
47	XY11LM018	11000	11000	0	0.00%	
48	XY11LM018	11000	11000	0	0.00%	
49	XY11LM018	11000	11000	0	0.00%	
50	XY11LM018	11000	11000	0	0.00%	

Safety is our serious job for our worker and engineer team

