

□□6061□□□□□□



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYA-130831&XYA-130901  
 Supplier : XY-GLOBAL

Inspection Date:11<sup>th</sup> Sep-, 2013  
 Inspector:LEO

Inspection only for: PO . XYA-130831&XYA-130901 Item No.400-01-038/400-01-075	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
400-01-038	432PCS	7% inspection	0pcs	No failure	432pcs
400-01-075	150PCS	7% inspection	0pcs	No failure	150pcs

**Appearance Inspection :**

No failure,

**Dimension Inspection:**

No failure , below measurement report for reference.


**Assembly Test:**

No failure

**Inspection Summary**

The inspection sample plan is 100% inspection.

Digital photo records :





1. Packing

2. Packing



3. Product:400-01-075

4. Product:400-01-075



5. Product :400-01-075

6. Product: 400-01-075

