

Inspection Report

Report No.: XYSL-140622
 Supplier : XY-GLOBAL

Inspection Date: 26th Jul, 2014
 Inspector: Leo

Inspection only for: PO . XYSL-140622 Item No. XY11WD044	Inspection Result: PASS
-------------------------------------------------------------	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD044	10000PCS	5% inspection	0pcs	No failure	10000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product	6. The test report

Part Name	Part Name: ADC12 A380
Material	Material: ADC12 A380
Surface	Surface: nickle
Tolerance	Tolerance: +/- 0.01
MOQ	MOQ: 100
Lead Time	Lead Time: 25-30 days
Specification	Specification: OEM service
Accessories	Accessories: included
Certification	Certification: ISO 9001, EU, etc.
Finish	Finish: as requested
Quality Control	Quality Control: strict
Payment Terms	Payment Terms: T/T
OEM	OEM service available