

**Inspection Report**

Report No.: XYZI-140328  
 Supplier : XY-GLOBAL

Inspection Date: 24<sup>th</sup> Apr, 2014  
 Inspector: Leo

|  |                                   |
|--|-----------------------------------|
| Inspection only for:<br>PO . XYZI-140328 Item No.1400351 | <u>Inspection Result:</u><br>PASS |
|--|-----------------------------------|

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| 1400351     | 6000PCS       | 1% inspection | 0pcs         | No failure          | 6000pcs         |

|  |
|--|
| <b>Appearance Inspection :</b><br>No failure,  |
| <b>Dimension Inspection:</b><br>No failure , below measurement report for reference. |
| <b>Assembly Test:</b><br>No failure  |
| <b>Inspection Summary</b><br>The inspection sample plan is 100% inspection.          |

Digital photo records :

|   |   |
|---|---|
|   |   |
| 1. Packing  | 2. Product  |
|  |  |
| 3. Product  | 4 Product   |
|  |  |
| 5. Product:   | 6. Product:   |

