

Inspection Report

Report No.: XYKI-140302
Supplier: XY-GLOBAL

Inspection Date: 7th Apr, 2014
Inspector: Leo

Inspection only for: PO . XYKI-140302 Item No.1900031	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1900031	6000PCS	1% inspection	0pcs	No failure	5000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	ADC12 A380 CNC加工品
仕様	ADC12 A380
数量	1000個
納期	受注後10営業日
加工方法	CNC加工
公差	±0.01mm
MOQ	1000個
表面処理	ニッケルメッキ
検査	寸法検査
包装	10個/箱
送料	別途見積
備考	1. Name: ADC12 A380 CNC加工品 2. Process: CNC加工 3. Material: ADC12 A380 4. Surface: ニッケルメッキ 5. Tolerance: ±0.01mm 6. 数量: 1000個 7. Specification: OEMサービス 8. 納期: 25-30日 9. 付属品: 付属品あり 10. 規格: Austrial EU 11. ISO 9001 ISO 9001:2015 2. 表面処理: 別途見積 3. 表面処理: finishment kinds available 4. 数量: 1000個 5. 納期: 25-30日 6. 送料: 別途見積 7. 検査: 寸法検査 ISO 9001 OEMサービス