

Inspection Report

Report No.: XYKI-140316
Supplier : XY-GLOBAL

Inspection Date: 17th Apr, 2014
Inspector: Leo

| | |
|---|-----------------------------------|
| Inspection only for: PO . XYKI-140316 Item No.300490 | Inspection Result: PASS |
|---|-----------------------------------|

| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| 300490 | 10000PCS | 1% inspection | 0pcs | No failure | 10000pcs |

| |
|--|
| Appearance Inspection : No failure, |
| Dimension Inspection: No failure , below measurement report for reference. |
| Assembly Test: No failure |
| Inspection Summary The inspection sample plan is 100% inspection. |

| | |
|---|---|
| Digital photo records : | |
|  |  |
| 1. Packing | 2. Product |
|  |  |
| 3. Product | 4 Product |
|  |  |
| 5. Product: | 6. Product: |

| | |
|-----------------|----------------------------|
| 品名 | ADC12 A380 CNC加工品 |
| 仕様 | ADC12 A380 |
| 数量 | 100個 |
| 納期 | 受注後10営業日以内 |
| 加工方法 | CNC加工 |
| 公差 | ±0.01mm |
| MOQ | 100個 |
| 表面処理 | ニッケルメッキ |
| 検査 | 寸法検査 |
| 包装 | 20-25個/箱 |
| 送料 | 別途見積 |
| 1.Name | ADC12 A380 CNC加工品 |
| 2.Process | CNC加工 |
| 3.Material | ADC12 A380 |
| 4.Surface | ニッケルメッキ |
| 5.Tolerance | ±0.01mm |
| 6.数量 | 100個 |
| 7.Specification | OEM仕様 |
| 8.納期 | 25-30日 |
| 9.付属品 | accessories |
| 10.認証 | Austrial EU |
| 11.規格 | ISO 9001 |
| ISO | 1. 10mm |
| 2.仕様 | |
| 3. surface | finishment kinds available |
| 4.数量 | |
| 5.納期 | |
| 6.送料 | |
| 7.検査 | |
| 8.包装 | |
| 9.規格 | ISO9001 |
| 10.認証 | |
| OEM | |