

Inspection Report

Report No.: XYSL-130515
 Supplier : XY-GLOBAL

Inspection Date: 12th Jun, 2013
 Inspector: Leo

Inspection only for: PO . XYSL-130515 Item No. XY11SL008	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11SL008	6000PCS	5% inspection	0pcs	No failure	6000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product	6. The test report

品名	加工品 加工品 加工品 加工品 OEM加工品
品名	ADC12 A380
品名	
品名	
品名	CNC
品名	CNC
品名	gague
MOQ	
公差	+/- 0.01
公差	T / T 50
公差	CNC
公差	
公差	
公差	20-25 T / T 50
公差	
1.Name	OEM
2.Process	CNC
3.Material	ADC12 A380
4.Surface	nickle
5.Tolerance	+/- 0.01
6.	100
7.Specification	OEM serice
8.	25 30
9.	accessoried
10.	Austrial EU
11.	ISO 9001
ISO	1. 10
2.	
3. sureface	finishment kinds available
4.	
5.	
6.	
7.	
ISO	9001
OEM	