

Inspection Report






Report No.: XYK-140517
Supplier : XY-GLOBAL

Inspection Date: 12th Jun, 2014
Inspector: Ken

Inspection only for: PO . XYK-140517 Item No.XY-141708	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-141708	50000PCS	1% inspection	0pcs	No failure	50000pcs

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

ชื่อ	บริษัท ออโต้แมค จำกัด OEM
ชื่อ	ADC12 A380
ชื่อ	อะไหล่
รายละเอียด	อะไหล่เครื่องยนต์
ชื่อ	อะไหล่เครื่องยนต์
ชื่อ	CNC อะไหล่เครื่องยนต์
ชื่อ	อะไหล่เครื่องยนต์
MOQ	100
ความแม่นยำ	+/- 0.01mm
ระยะเวลา	T / T 50% 50% T / T
ชื่อ	CNC อะไหล่เครื่องยนต์
ชื่อ	อะไหล่เครื่องยนต์
ชื่อ	อะไหล่
ชื่อ	20-25 T / T 50%
ชื่อ	อะไหล่เครื่องยนต์
1. Name บริษัท OEM	
2. ชื่อ บริษัท CNC	
3. Material อะไหล่เครื่องยนต์ ADC12 A380	
4. รายละเอียด อะไหล่เครื่องยนต์	
5. ความแม่นยำ ±0.01mm	
6. MOQ 100	
7. บริการ OEM service	
8. ระยะเวลา 25-30	
9. รายละเอียด อะไหล่เครื่องยนต์	
10. ประเทศ Austria EU	
11. ISO 9001	
บริษัท	
1. ISO 10	
2. รายละเอียด	
3. รายละเอียด	
4. รายละเอียด	
5. รายละเอียด	
6. รายละเอียด	
7. รายละเอียด	
บริษัท	
รายละเอียด	
รายละเอียด ISO9001	
รายละเอียด	
บริษัท OEM	

บริษัท ออโต้แมค จำกัด