

Inspection Report

Report No.: XYSL-130516
 Supplier : XY-GLOBAL

Inspection Date: 14th Jun, 2013
 Inspector: Leo

Inspection only for: PO . XYSL-130516 Item No. XY11SL009	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11SL009	6000PCS	5% inspection	0pcs	No failure	6000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :



5. Product: 6. The test report

品名	ADC12 A380 OEM
仕様	ADC12 A380
材質	ADC12 A380
表面処理	nickle
公差	+/- 0.01
MOQ	100
納期	T / T 50
加工	CNC
精度	20-25 T / T 50
規格	ISO 9001
仕様	OEM service
数量	25/30
付属品	accessories
標準	Austrial EU
規格	ISO 9001
仕様	ISO 9001
表面	finishment kinds available
数量	4
仕様	
数量	6
仕様	
仕様	ISO 9001
仕様	OEM