

□□□□□□□□□□□□□□□□

**Inspection Report**

**Report No.:** XYS-130308  
**Supplier :** XY-GLOBAL

**Inspection Date:** 20<sup>th</sup> Apr, 2013  
**Inspector:** Leo

Inspection only for: PO . XYS-130308 Item No.XY-130014	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-130014	<b>10000PCS</b>	10% inspection	0pcs	No failure	10000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

ชื่อ	บริษัท อีซีซี จำกัด (มหาชน) OEM
ประเภท	ADC12 A380
วัสดุ	อลูมิเนียม
ขนาด	ตามแบบร่าง
สี	ตามแบบร่าง
กระบวนการ	CNC
ข้อกำหนด	ตามแบบร่าง gague
MOQ	100
ความแม่นยำ	+/- 0.01
ระยะเวลา	T / T 50% T / T
การรับประกัน	CNC
การชำระเงิน	ตามแบบร่าง
สถานที่	ตามแบบร่าง
เบอร์โทร	20-25 &nbsp; T / T 50
เว็บไซต์	www.aisc.co.th
1.Name	บริษัท อีซีซี จำกัด (มหาชน) OEM
2.Process	CNC
3.	ADC12 A380
4.Surface	ตามแบบร่าง nickel
5.Tolerance	+/- 0.01
6.	100
7.Specification	OEM
8.	25-30
9.	accessories
10.	Austrial EU
11 &nbsp;	ISO 9001
	ISO 10
2.	
3	sureface finishment kinds available
	4
5.	
	6
7.	
	&nbsp; T / T 50
	ISO9001
OEM	