

Inspection Report

Report No.: XYLA-150304
 Supplier : XY-GLOBAL

Inspection Date: 10th Apr, 2015
 Inspector: Leo

Inspection only for: PO . XYLA-150304 Item No. XY31PC003	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31PC003	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :
 No failure,

Dimension Inspection:
 No failure , below measurement report for reference.

Assembly Test:
 No failure

Inspection Summary
 The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product</p> 
<p>3. Product</p> 	<p>4 Product</p> 
<p>5. Product:</p>	<p>6. report</p>

品名	CNC加工 各種形状CNC加工品 各種形状CNC加工品 各種形状CNC加工品 各種形状CNC加工品 各種形状CNC加工品 各種形状CNC加工品
材質	アルミ AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 POM
仕様	各種仕様
数量	1 個単位
単位	個
加工	CNC 加工
表面	各種表面処理 gauge
MOQ	100
公差	+/- 0.01
納期	T / T 50% 前払い 50% T / T
加工	CNC 加工
単位	個
納期	2025 T / T 50%
加工	CNC 加工
1.Name OEM CNC	
2.Process CNC	
3.Material AL6061 AL6065 AL6063 AL7075 POM	
4.Surface 各種表面処理	
5.Tolerance +/- 0.01	
6.数量 100	
7.Specification OEM service	
8.納期 25-30	
9.加工 CNC accessoried	
10.加工 Austria EU	
11.加工 ISO 9001	
ISO 1. 10	
2. surface finishment kinds available	
3. 4.	
5.	
6.	
7.	
CNC	
CNC	
CNC ISO9001	
CNC	
CNC OEM	

Safety is our serious job for our worker and engineer team

