

Inspection Report

Report No.: XYFD-130804
Supplier : XY-GLOBAL

Inspection Date: 3th Sep-, 2013
Inspector: LEO

Inspection only for: PO . XYFD-130804 Item No.400-10-071	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
400-10-071	6000Set	100% inspection	0pcs	No failure	6000Set

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product :

00	CNC
00	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 POM
00	
0000	
00	
0000	CNC
0000	
MOQ	
00/000	+/- 0.01mm
000	T / T 50
0000	CNC CNC CNC CNC
00	CNC
000	
00	T / T 50 20 25
0000	CNC
1. OEM CNC	
2. CNC	
3. Material AL6061 AL6065 AL6063 AL7075 POM	
4. ±0.01mm	
5. 100	
7. OEM service	
8. 25-30	
9. CNC	
10. Austria EU	
11. ISO 9001	
000 00	
1. ISO 10	
2.	
4.	
5.	
6.	
7.	
CNC	
CNC	
CNC ISO9001	
CNC	
CNC OEM	

[Oem oem](#)