

**Inspection Report**

**Report No.:** XYN-140528  
**Supplier :** XY-GLOBAL

**Inspection Date:** 23<sup>th</sup> Jun, 2014  
**Inspector:** Ken

Inspection only for: PO . XYN-140528 Item No.200870	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
200870	20000PCS	1% inspection	0pcs	No failure	20000pcs

<b>Appearance Inspection :</b>
No failure.
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

