



XY Electronics Technology Co., Ltd

### Inspection Report

Report No.: XYF-130811  
Supplier : XY-GLOBAL

Inspection Date:5<sup>th</sup> Sep-, 2013  
Inspector:LEO

Inspection only for: PO . XYF-130811      Item No.300276	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
300276	10000Set	100% inspection	0pcs	No failure	10000Set

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing	2. Product
3. Product:	4. Product:
5. Product :	6. inspection reports

