

**Inspection Report**

Report No.: XYAN-150302  
 Supplier : XY-GLOBAL

Inspection Date: 1<sup>th</sup> Apr-, 2015  
 Inspector: LEO

Inspection only for: PO . XYBA-150302    Item No. XY21ZC088	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC088	6800pcs	7% inspection	0pcs	No failure	6800pcs

<b>Appearance Inspection :</b> No failure.
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:



Safety is our serious job for our worker and engineer team

