



**Inspection Report**

**Report No.:** XYN-140524  
**Supplier :** XY-GLOBAL

**Inspection Date:** 19<sup>th</sup> Jun, 2014  
**Inspector:** Ken

Inspection only for: PO . XYN-140524 Item No.XY-142537	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-142537	10000PCS	1% inspection	0pcs	No failure	10000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

品名	<a href="#">CNC精密加工</a> ・ <a href="#">OEM</a>
品番	ADC12/A380
用途	
仕様	
材質	CNC
加工	CNC加工
加工	gague
MOQ	
公差	+/- 0.01
リードタイム	T / T 50
加工	CNC
品質保証	
加工	
加工	20-25 / T 50
加工	<a href="#">CNC</a>
1.Name <a href="#">CNC精密加工</a>	
2.Process <a href="#">CNC</a>	
3. <a href="#">ADC12/A380</a>	
4.Surface <a href="#">nickle</a>	
5.Tolerance <a href="#">+/- 0.01</a>	
6 <a href="#">100</a>	
7.Specification <a href="#">OEM</a>	
8 <a href="#">25-30</a>	
9 <a href="#">accessoried</a>	
10 <a href="#">Austrial</a> <a href="#">EU</a>	
11 <a href="#">ISO 9001</a>	
<a href="#">CNC</a>	
ISO <a href="#">10</a>	
2 <a href="#">kindls</a> <a href="#">available</a>	
3 sureface <a href="#">4</a>	
5 <a href="#">6</a>	
7 <a href="#">ISO 9001</a>	
<a href="#">OEM</a>	
<a href="#">ISO 9001</a>	
<a href="#">OEM</a>	