



**Inspection Report**

Report No.: XYFA-140916  
 Supplier : XY-GLOBAL

Inspection Date: 15<sup>th</sup> Oct-, 2014  
 Inspector: LEO

Inspection only for: PO . XYFA-140916    Item No. XY21ZC072	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC072	8000pcs	7% inspection	0pcs	No failure	8000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

品名	CNC加工 各種形状のCNC加工品 各種形状のCNC加工品 各種形状のCNC加工品 各種形状のCNC加工品 各種形状のCNC加工品 各種形状のCNC加工品
材質	アルミニウム AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 POM
形状	各種形状
用途	各種用途
加工	各種加工
加工機	CNC加工機
加工条件	各種加工条件
MOQ	100個
公差	+/- 0.01mm
納期	T / T 50% 前 / T / T 100%
加工方法	CNC加工
加工精度	±0.01mm
加工時間	20~25日 T / T 50%
加工機	CNC加工機
1. Name OEM CNC加工品	
2. Process CNC加工	
3. Material AL6061 AL6065 AL6063 AL7075 POM	
4. Surface 各種表面処理	
5. Tolerance +/- 0.01mm	
6. 各種形状 100個	
7. Specification OEM service	
8. 各種形状 25~30日	
9. 各種形状 CNC加工 accessories	
10. 各種形状 Austrial EU	
11. ISO 9001	
ISO 9001	
1. 各種形状	
2. 各種形状	
3. surface finishment kinds available	
4. 各種形状	
5. 各種形状	
6. 各種形状	
7. 各種形状	
8. 各種形状	
CNC加工	
CNC加工	
CNC加工 ISO9001	
CNC加工	
CNC加工 OEM	

Safety is our serious job for our worker and engineer team

