



**Inspection Report**

Report No.: XYSK-140512  
 Supplier : XY-GLOBAL

Inspection Date: 15<sup>th</sup> Jun, 2014  
 Inspector: Leo

Inspection only for: PO . XYSK-140512 Item No. XY11WD014	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD014	12000PCS	1% inspection	0pcs	No failure	12000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Dimensions report

品名	品名 数量単位OEM品
品名	品名 ADC12A380
品名	品名
品名	品名
品名	CNC加工品
品名	CNC加工品
品名	品名
MOQ	品
寸法	+/- 0.01
寸法	T / T 50 50 T / T
寸法	CNC加工品
寸法	品名
寸法	品名
寸法	20-25 T / T 50
寸法	品名
1.Name	OEM品
2.Process	CNC加工品
3.Material	ADC12A380
4.Surface	nickle
5.Tolerance	+/- 0.01
6	100
7.Specification	OEM service
8	25 30
9	accessoried
10	Austrial EU
11	ISO 9001
ISO	1. 10
2	
3. surface	finishment kinds available
	4.
5	
	6.
7	
	ISO9001
OEM	