

**Inspection Report**

Report No.: XYAN-150303  
 Supplier : XY-GLOBAL

Inspection Date: 1<sup>st</sup>- Apr-, 2015  
 Inspector: LEO

Inspection only for: PO . XYBA-150303      Item No. XY21ZC090	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC090	8000pcs	7% inspection	0pcs	No failure	8000pcs

**Appearance Inspection :**  
 No failure.

**Dimension Inspection:**  
 No failure , below measurement report for reference.

**Assembly Test:**  
 No failure

**Inspection Summary**  
 The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product:</p> 
<p>3. Product:</p> 	<p>4. Product:</p> 
<p>5. Product :</p>	<p>6. Inspection report:</p>



Safety is our serious job for our worker and engineer team

