

**Inspection Report**

Report No.: XYSL-140609  
 Supplier : XY-GLOBAL


Inspection Date: 10<sup>th</sup> Jul, 2014  
 Inspector: Leo

Inspection only for: PO . XYSL-140609 Item No. XY11WD033	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD033	10000PCS	5% inspection	0pcs	No failure	10000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product</p> 
<p>3. Product</p> 	<p>4 Product</p> 
<p>5. Product:</p>	<p>6. The test report</p>

Part Name	OEM Part Name
Material	ADC12/A380
Surface	nickel
Tolerance	+/- 0.01
MOQ	100
Lead Time	25/30
MOQ	100
Lead Time	20/25
MOQ	100
1.Name OEM Part Name	
2.Process CNC	
3.Material ADC12/A380	
4.Surface nickel	
5.Tolerance +/- 0.01	
6.MOQ 100	
7.Specification OEM service	
8.Lead Time 25/30	
9.Accessories	
10.Austrial EU	
11.ISO 9001	
ISO 1. 10	
2. sureface finishment kinds available	
3. 4.	
5.	
6.	
7.	
8.	
9. ISO9001	
10. OEM	