





Inspection Report

Report No.: XYK-130829
 Supplier : XY-GLOBAL







Inspection Date: 29th Sep-, 2013
 Inspector: LEO

Inspection only for: PO . XYK-130829 Item No.1330026	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1330026	50PCS	100% inspection	0pcs	No failure	50pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

