

Inspection Report

Report No.: XYKB-140521
 Supplier : XY-GLOBAL

Inspection Date: 15th Jun, 2014
 Inspector: Leo

Inspection only for: PO . XYKB-140521 Item No. XY72YM017	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM017	1000PCS	1% inspection	0pcs	No failure	1000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	 
5. Product:	6. Dimensions report:

