

Inspection Report

Report No.: XYN-130814
 Supplier : XY-GLOBAL

Inspection Date:02th- Sep-, 2013
 Inspector:LEO

Inspection only for: PO . XYN-130814 Item No.1400190	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1400190	5000PCS	1% inspection	0pcs	No failure	5000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
1. Packing	2. Product:
3. Product:	4. Product:
5. Product :	6. Product:

