



**Inspection Report**

**Report No.:** XYDS-140618  
**Supplier :** XY-GLOBAL

**Inspection Date:** 15<sup>th</sup> July, 2014  
**Inspector:** Leo

Inspection only for: PO . XYDS-140618 Item No.801-30-210	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
801-30-210	10000PCS	1% inspection	0pcs	No failure	10000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product

