

Inspection Report

Report No.: XYNK-130813
Supplier : XY-GLOBAL

Inspection Date: 7th Sep-, 2013
Inspector: LEO

| | |
|---|-----------------------------------|
| Inspection only for: PO . XYNK-130813 Item No.1390257 | <u>Inspection Result:</u> PASS |
|---|-----------------------------------|

| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|-----------------|--------------|---------------------|-----------------|
| 1390257 | 5000PCS | 100% inspection | 0pcs | No failure | 5000pcs |

| |
|--|
| Appearance Inspection : |
| No failure, |
| Dimension Inspection: |
| No failure , below measurement report for reference. |
| Assembly Test: |
| No failure |
| Inspection Summary |
| The inspection sample plan is 100% inspection. |

| | |
|---|---|
| Digital photo records : | |
|  |  |
| 1. Packing | 2. Product: |
|  |  |
| 3. Product: | 4. Product: |
|  |  |
| 5. Product : | 6. Product: |

