

**Inspection Report**







Report No.: XYSL-130513  
 Supplier : XY-GLOBAL

Inspection Date: 12<sup>th</sup> Jun, 2013  
 Inspector: Leo

Inspection only for: PO . XYSL-130513 Item No. XY11SL007	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11SL007	6000PCS	5% inspection	0pcs	No failure	5000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. The test report

製品名	アダプタ (アダプター) の製造/加工 OEM/ODM/モジュール
部品名	ADC12 A380
仕様	
材質	アルミニウム (Aluminum)
表面処理	ニッケルメッキ (Nickel Plating)
公差	CNC 加工 0.01mm
MOQ	100個
公差	+/- 0.01mm
納期	T / T 50% / T 50%
公差	CNC 加工 0.01mm
公差	
公差	
公差	20-25 T / T 50%
公差	
1.Name	OEM
2.Process	CNC
3.Material	ADC12 A380
4.Surface	nickel
5.Tolerance	+/- 0.01
6.	100
7.Specification	OEM service
8.	25 30
9.	accessories
10.	Austrian EU
11.	ISO 9001
ISO	1. 10
2.	
3. surface	finishment kinds available
	4.
5.	
	6.
7.	
	ISO9001
OEM	