

Inspection Report

Report No.: XYSL-130504
 Supplier : XY-GLOBAL

Inspection Date: 2th Jun, 2013
 Inspector: Leo

Inspection only for: PO . XYSL-130504 Item No. XY11SL002	<u>Inspection Result:</u> PASS
---	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11SL002	1000PCS	5% inspection	0pcs	No failure	1000pcs

Appearance Inspection :
 No failure,

Dimension Inspection:
 No failure , below measurement report for reference.

Assembly Test:
 No failure

Inspection Summary
 The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. The test report

