

Inspection Report

Report No.: XYDA-140504
 Supplier : XY-GLOBAL

Inspection Date: 1st Jun, 2014
 Inspector: Leo

Inspection only for: PO . XYDA-140504 Item No.1493768	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1493768	15000PCS	1% inspection	0pcs	No failure	15000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

