

**Inspection Report**

Report No.: XYSK-140623  
 Supplier : XY-GLOBAL

Inspection Date: 15<sup>th</sup> July, 2014  
 Inspector: Leo

Inspection only for: PO . XYSK-140623 Item No. XY31SY020	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY020	20000PCS	1% inspection	0pcs	No failure	20000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :



