

Inspection Report

Report No.: XYDA-140512
 Supplier : XY-GLOBAL

Inspection Date: 6th Jun, 2014
 Inspector: Leo

Inspection only for: PO . XYDA-140512 Item No.701254	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
701254	3000PCS	1% inspection	0pcs	No failure	3000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	ADC12 A380 CNC加工品
仕様	ADC12 A380
数量	100個
納期	約 20-25日
加工方法	CNC加工
公差	+/- 0.01mm
表面処理	ニッケルメッキ
検出	100%
仕様書	OEM仕様書
梱包	25個/箱
付属品	accessories
認証	Austrial EU
規格	ISO 9001
備考	
ISO	1. 10mm
2.	
3. surface	finishment kinds available
4.	
5.	
6.	
7.	
8.	
9.	
10.	ISO9001
11.	
OEM	