

Inspection Report

Report No.: XYSK-140605
 Supplier : XY-GLOBAL

Inspection Date: 2th July, 2014
 Inspector: Leo

Inspection only for: PO . XYSK-140605 Item No. XY31SY005	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY005	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	 深圳市真朴电子科技有限公司 XY Electronics Technology Co.,Ltd 
5. Product:	6. report

品名	CNC 部品
品番	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 POM
材質	
仕様	
公差	+/- 0.01
MOQ	
納期	T / T 50%
加工方法	CNC
表面処理	nickle
1. Name	OEM CNC
2. Process	CNC
3. Material	AL6061 AL6065 AL6063 AL7075 POM
4. Surface	nickle
5. Tolerance	+/- 0.01
6. Quantity	100
7. Specification	OEM service
8. Lead time	25-30
9. Accessory	accessories
10. Standard	Austrial EU
11. ISO	ISO 9001
ISO	1. 10
2. Surface	finishment kinds available
3. Surface	finishment kinds available
4. Quantity	
5. Lead time	
6. Accessory	
7. Standard	
8. ISO	ISO 9001
9. Service	OEM