

Inspection Report

Report No.: XYKB-140523
Supplier : XY-GLOBAL

Inspection Date: 17th Jun, 2014
Inspector: Leo

Inspection only for: PO . XYKB-140523 Item No. XY72YM019	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM019	1000PCS	1% inspection	0pcs	No failure	1000pcs

Appearance Inspection :
No failure,

Dimension Inspection:
No failure , below measurement report for reference.

Assembly Test:
No failure

Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product</p> 
<p>3. Product</p> 	<p>4 Product</p> 
<p>5. Product:</p>	<p>6. Dimensions report:</p>

品名	ADC12 A380 CNC加工品 OEM受注品
品名	ADC12 A380
仕様	
材質	ADC12 A380
加工	CNC加工
表面処理	ニッケルメッキ
公差	+/- 0.01mm
MOQ	100個
納期	T / T 50% 前払 / T / T 50%
梱包	10個/箱
備考	
1.Name	OEM受注品
2.Process	CNC加工
3.Material	ADC12 A380
4.Surface	ニッケルメッキ
5.Tolerance	+/- 0.01mm
6.数量	100個
7.Specification	OEM受注品
8.納期	25/30日
9.付属品	accessories
10.規格	Austrial EU
11.品質	ISO 9001
ISO	1. 10年保証
2.保証	
3. surface finishment	kindls available
4.仕様	
5.仕様	
6.仕様	
7.仕様	
8.仕様	
9.仕様	
10.仕様	ISO9001
11.仕様	
OEM	受注品