

**Inspection Report**

Report No.: XYDA-150311  
 Supplier : XY-GLOBAL

Inspection Date: 4<sup>th</sup> Apr, 2015  
 Inspector: Leo

Inspection only for: PO . XYDA-150311 Item No. XY31CY029	Inspection Result: <b>PASS</b>
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY029	30000PCS	1% inspection	0pcs	No failure	30000pcs

**Appearance Inspection :**  
 No failure,

**Dimension Inspection:**  
 No failure , below measurement report for reference.

**Assembly Test:**  
 No failure

**Inspection Summary**  
 The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing	2. Product												
3. Product	4 Product												
	 深圳市真朴电子科技有限公司 XY Electronics Technology Co.,Ltd <table border="1"> <tr> <td>Product Name</td> <td>XY31CY029</td> <td>Revision Date</td> <td>2015.04.04</td> </tr> <tr> <td>Product Type</td> <td>XY31CY029</td> <td>Revision Date</td> <td>2015.04.04</td> </tr> <tr> <td>Product Code</td> <td>XY31CY029</td> <td>Revision Date</td> <td>2015.04.04</td> </tr> </table>	Product Name	XY31CY029	Revision Date	2015.04.04	Product Type	XY31CY029	Revision Date	2015.04.04	Product Code	XY31CY029	Revision Date	2015.04.04
Product Name	XY31CY029	Revision Date	2015.04.04										
Product Type	XY31CY029	Revision Date	2015.04.04										
Product Code	XY31CY029	Revision Date	2015.04.04										
5. Product:	6. report												

