

Inspection Report

Report No.: XYR-130812
Supplier : XY-GLOBAL

Inspection Date:09th Sep-, 2013
Inspector:LEO

Inspection only for: PO . XYR-130812 Item No.1420210	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1420210	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

