

**Inspection Report**

Report No.: XYI-140320  
 Supplier : XY-GLOBAL









Inspection Date: 17<sup>th</sup> Apr, 2014  
 Inspector: Leo

Inspection only for: PO . XYI-140320 Item No.142089	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
142089	40000PCS	1% inspection	0pcs	No failure	40000pcs

<b>Appearance Inspection :</b> No failure.
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:
	
7. Product:	8. Report:

