

Inspection Report







Report No.: XYDK-140520
 Supplier : XY-GLOBAL

Inspection Date: 13th Jun, 2014
 Inspector: Leo

Inspection only for: PO . XYDK-140520 Item No.200-01-380	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
200-01-380	10000SET	1% inspection	0pcs	No failure	10000SET

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	ADC12 A380 CNC加工品
仕様	ADC12 A380
数量	100個
納期	約 20-25日
加工方法	CNC加工
公差	+/- 0.01mm
表面処理	ニッケルメッキ
検査	ISO 9001
備考	OEM受注可
品名	ADC12 A380 CNC加工品
仕様	ADC12 A380
数量	100個
納期	約 20-25日
加工方法	CNC加工
公差	+/- 0.01mm
表面処理	ニッケルメッキ
検査	ISO 9001
備考	OEM受注可
1.Name	ADC12 A380 CNC加工品
2.Process	CNC加工
3.Material	ADC12 A380
4.Surface	ニッケルメッキ
5.Tolerance	+/- 0.01mm
6.数量	100個
7.Specification	OEM受注可
8.納期	約 25-30日
9.加工方法	CNC加工
10.公差	+/- 0.01mm
11.表面処理	ニッケルメッキ
ISO	ISO 9001
1. 仕様	ADC12 A380
2. 数量	100個
3. 表面処理	ニッケルメッキ
4. 公差	+/- 0.01mm
5. 納期	約 20-25日
6. 加工方法	CNC加工
7. 検査	ISO 9001
備考	OEM受注可
ISO	ISO 9001
備考	OEM受注可