

Inspection Report

Report No.: XYFD-130804
Supplier : XY-GLOBAL

Inspection Date: 3th Sep-, 2013
Inspector: LEO

Inspection only for: PO . XYFD-130804 Item No.400-10-071	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
400-10-071	6000Set	100% inspection	0pcs	No failure	6000Set

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product :

000000	CNC 0000000000CNC0000000000000000 00000000000000CNC0000000000CNC0000 00 00CNC0000000000000000CNC000000CNC
000000	000AL6061 AL60650AL60630AL70750SUS3040SUS3030SUS3160POM00
0000	000000000000
0000	00000000 0000000000000000000000000000
000000	000000000000000000
0000	CNC000CNC 000000
0000000	000 000
MOQ	00
00/00	+/- 0.010000000
000	T / T 500500T / T0000000000;00
0000000000	CNC00000000CNC0000CNC0000CNC0000 000 00
0000000000	000 CNC000000000 000000
0000	000000
00	20-250T / T 500000000
000000	CNC00000000
1.Name0 0000000000OEM CNC00000000	
2.Process0000000000CNC000000	
3.Material0AL6061 AL60650AL60630AL70750POM00	
4.Surface000 nickle000000 000000000	
5.Tolerance000+/- 0.01000	
600000000000000000001000000	
7.Specification0OEM0serice000	
8.0000000000000000000000250300000	
9.0000000000CNC000 accessoried000	
10.00000000000000000000Austrial0EU00	
11.000ISO 9001	
0000 00	
ISO001. 10000000	
2.000	
3. sureface0finishment0000kindls0abailable00	
000	
4.000	
5.00000000	
00006.00000	
7.000	
0000. 0000	
CNC000	
CNC0000000000000000	
CNC0000000000000000ISO9001	
CNC000	
CNC0000000000000000OEM0000000000	