

Inspection Report

Report No.: XYN-131111  
 Supplier : XY-GLOBAL

Inspection Date: 4<sup>th</sup> Dec-, 2013  
 Inspector:KEN

Inspection only for: PO . XYN-131111 Item No.XY-MST-027	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-MST-027	10000PCS	1% inspection	0pcs	No failure	10000pcs

<b>Appearance Inspection :</b> No failure.
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product.
	
3. Product:	4. Product:
	
5. Product :	6. Product:

