

Inspection Report

Report No.: XYSL-130517
 Supplier : XY-GLOBAL





Inspection Date: 15th Jun, 2013
 Inspector: Leo

Inspection only for: PO . XYSL-130517 Item No. XY11SL010	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11SL010	6000PCS	5% inspection	0pcs	No failure	6000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product</p> 
<p>3. Product</p> 	<p>4 Product</p> 
<p>5. Product:</p>	<p>6. The test report</p>

