

Inspection Report

Report No.: XYKB-140515
 Supplier : XY-GLOBAL

Inspection Date: 11th Jun, 2014
 Inspector: Leo

Inspection only for: PO . XYKB-140515 Item No. XY72YM011	<u>Inspection Result:</u> PASS
---	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM011	3000PCS	1% inspection	0pcs	No failure	3000pcs

Appearance Inspection :
 No failure,

Dimension Inspection:
 No failure , below measurement report for reference.

Assembly Test:
 No failure

Inspection Summary
 The inspection sample plan is 100% inspection.

Digital photo records :

																															
1. Packing	2. Product																														
																															
3. Product	4 Product																														
	<p>XY-GLOBAL 深圳市武林电子科技有限公司 XY Electronics Technology Co.,Ltd</p> <table border="1"> <tr> <td>Organization</td> <td>XY Electronics Technology Co., Ltd</td> <td>Product Name</td> <td>XY72YM011</td> <td>Inspection Date</td> <td>2014.6.11</td> </tr> <tr> <td>Part No</td> <td>XY72YM011</td> <td>Lot No</td> <td>14051501</td> <td>Inspection Place</td> <td>XY-GLOBAL</td> </tr> <tr> <td>Part Name</td> <td>XY72YM011</td> <td>Lot No</td> <td>14051501</td> <td>Inspection Date</td> <td>2014.6.11</td> </tr> </table> <p>Inspection Result: PASS</p> <p>Inspection Summary: No defect found.</p> <table border="1"> <thead> <tr> <th>Item No.</th> <th>Item Name</th> <th>Inspection Result</th> <th>Inspection Method</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>外观检查</td> <td>合格</td> <td>目视</td> </tr> <tr> <td>2</td> <td>尺寸检查</td> <td>合格</td> <td>卡尺</td> </tr> </tbody> </table> <p>XY-GLOBAL 深圳市武林电子科技有限公司 XY Electronics Technology Co.,Ltd</p>	Organization	XY Electronics Technology Co., Ltd	Product Name	XY72YM011	Inspection Date	2014.6.11	Part No	XY72YM011	Lot No	14051501	Inspection Place	XY-GLOBAL	Part Name	XY72YM011	Lot No	14051501	Inspection Date	2014.6.11	Item No.	Item Name	Inspection Result	Inspection Method	1	外观检查	合格	目视	2	尺寸检查	合格	卡尺
Organization	XY Electronics Technology Co., Ltd	Product Name	XY72YM011	Inspection Date	2014.6.11																										
Part No	XY72YM011	Lot No	14051501	Inspection Place	XY-GLOBAL																										
Part Name	XY72YM011	Lot No	14051501	Inspection Date	2014.6.11																										
Item No.	Item Name	Inspection Result	Inspection Method																												
1	外观检查	合格	目视																												
2	尺寸检查	合格	卡尺																												
5. Product:	6. Dimensions report:																														

