

Inspection Report

Report No.: XYSL-130525
 Supplier : XY-GLOBAL

Inspection Date: 27th Jun, 2013
 Inspector: Leo

Inspection only for: PO . XYSL-130525 Item No. XY11SL015	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11SL015	10000PCS	5% inspection	0pcs	No failure	10000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. The test report

品名	部品名 部品番号
品名	ADC12 A380
品名	
品名	
品名	CNC
品名	CNC
品名	gague
MOQ	
公差	+/- 0.01
公差	T / T 50
公差	CNC
公差	
公差	20-25 T / T 50
公差	
1.Name	OEM
2.Process	CNC
3.Material	ADC12 A380
4.Surface	nickle
5.Tolerance	+/- 0.01
6	100
7.Specification	OEM serice
8	25 30
9	accessoried
10	Austrial EU
11	ISO 9001
ISO	1. 10
2	
3. sureface	finishment kinds available
4	
5	
6	
7	
8	
9	
10	ISO9001
11	
OEM	